Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2331Work Order Type: WeatherizationAudit Name: 14014SO2331

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO2331 DECHERD, TN 37324

Alt. Client ID: FRANKLIN

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Client Name:
Client ID: 14014SO2331
Alt. Client ID: FRANKLIN

Work Order (Bid Form)
Work Order Name: 14014SO2331

Report Run On: 5/28/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 3

Measures

Measure 1 Infi	Itration Redctn			Componen	ts		1	Inspected	
	L DUCT WORK AT REG								
2. W/S	FRONT DOOR / INSTAL	L DOOR I	OCK S			R			
			Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Miscellaneous Supplies	Infiltration Reduction	Each	1						
2 Labor	LABOR	Hour							
Other Detail									
			Measure	e Sub Total:			Sub Total:		
Measure 2 DW	/H Pipe Insulation			Componen	ts			Inspected	
	/H Pipe Insulation			Componen	ts			Inspected	
Measure 2 DW Comment	/H Pipe Insulation			Componen Estimated			Actual	Inspected	
	/H Pipe Insulation Description / Comment	Units	Qty	•		Qty		Inspected	
Comment		<i>Units</i> Each		Estimated	<u> </u>	Qty	Actual		
Comment # Material / Labor	Description / Comment		Qty	Estimated	<u> </u>	Qty	Actual		
# Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	<u> </u>	Qty	Actual		
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	<u> </u>	Qty	Actual		
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	<u> </u>	Qty	Actual		
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated	<u> </u>		Actual		
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost		
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost		
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost		

Report Run On: 5/28/2010

Measure 3 PressureRelief Piping Needed Comment		ed		Componen	its			Inspected
Joniment			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Pressure relief piping	Each	1					
2 Labor	Labor	Hour	1					
Other Detail]		
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								
Measure 4 Smo	ke Detector is Needed			Componen				Inspected
		Units		Estimated		Qty	Actual	Inspected
Comment # Material / Labor	ke Detector is Needed Description / Comment Smoke / Carbon detector	Units Each	Qty 1	•	1	Qty		
Comment # Material / Labor 1 Health and Safety Items	Description / Comment		Qty	Estimated	1	Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items	Description / Comment Smoke / Carbon detector	Each	Qty 1	Estimated	1	Qty	Actual	
# Material / Labor Health and Safety Items Labor	Description / Comment Smoke / Carbon detector	Each	Qty 1	Estimated	1	Qty	Actual	
# Material / Labor Health and Safety Items Labor	Description / Comment Smoke / Carbon detector	Each	Qty 1	Estimated	1		Actual Unit Cost	
# Material / Labor Health and Safety Items Labor	Description / Comment Smoke / Carbon detector	Each Hour	Qty 1 1	Estimated	1		Actual	
# Material / Labor Health and Safety Items Labor	Description / Comment Smoke / Carbon detector	Each Hour	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	

Report Run On: 5/28/2010